

Cedar Grove Subdivision Improvements



Cedar Grove Subdivision Improvements - Background


Residents of Cedar Grove Subdivision have raised concerns regarding the deteriorating condition of roadways within the neighborhood. Specifically, surface depressions and uneven pavement have been reported, posing potential safety hazards for both motorists and pedestrians.

A geotechnical report, prepared by CQC Engineering, identified specific areas of surface depression within the subdivision. These depressions are attributed to underlying heavy clay soils and will require targeted remediation to ensure long-term stability and safety.

Coordination between the City and El Paso Water also revealed failures within the storm drain system that contribute to and exacerbate the existing roadway issues.



Cedar Grove Existing Conditions







Cedar Grove Existing Conditions







Scope of Work

- The recommended course of action includes
 - Storm drain repairs
 - Select soil remediation
 - HMAC and base course repairs
 - Replacement of ADA sidewalks and driveways
 - Subdivision pavement seal coat



Recommendation

The authorization of budget transfer to utilize investment interest funds to set up the budget for the Cedar Grove Subdivision Improvements.



MISSION



Deliver exceptional services to support a high quality of life and place for our community.

VISION



Develop a vibrant regional economy, safe and beautiful neighborhoods and exceptional recreational, cultural and educational opportunities powered by a high performing government.



VALUES

Integrity, Respect, Excellence,
Accountability, People

MISIÓN



Brindar servicios excepcionales para respaldar una vida y un lugar de alta calidad para nuestra comunidad

VISIÓN



Desarrollar una economía regional vibrante, vecindarios seguros y hermosos y oportunidades recreativas, culturales y educativas excepcionales impulsadas por un gobierno de alto desempeño



VALORES

Integridad, Respeto, Excelencia, Responsabilidad, Personas